

AAR Comments for the Mark II – M2HB Mount for Shielded Guns

Issue – Mount placement on the gun

Discussion – The mount is placed on the .50 cal forward of the feed cover. This location makes it difficult to acquire a target using a day sight when it is that far forward. The placement for a laser is optimum, however.

Recommendation – Modify the design to keep the laser mounted forward and on the side of the weapon. The day sights should be placed on top of the feed tray for optimum use.

Issue – Durability

Discussion – There were no issues with durability with this mounting system. Approximately 6,000 rounds were fired through the weapon with the mount in place, and the mounting screws were not jarred loose, and the optics kept zeroed throughout.

Recommendation – No changes to durability design.

Issue – M2 EOTech Holo Sight

Discussion – The M2 EO Tech Holo Sight worked very well. All students were very impressed with the system and its ability to improve the gunner's marksmanship.

Recommendation – Purchase the sight for the battalion's .50 caliber machine guns.